

Current and voltage - our passion

File name: WD-D001-E



Bushing unpacking and lifting

Open the crate and remove the deep drawers and rafters
Check all material against packing list
Remove all components



Check / Remove all the documents





If necessary, fix an eyebolt on the terminal (not in MGC scope of supply)

The eyebolt fixed on the flange is furnished with the bushing.

Small bushing can be lifted by hand.







Current and voltage - our passion





